



Figure 16 (section a) Existing shoreline defences – Chichester Harbour
Ref: V3-Fig 16

Figure 16 (section b)

- the M275 and M27/A27 revetments are generally in reasonable condition, but require maintenance. Areas with original filled textile mattress armouring will eventually need upgrading to a suitable flexible block system