

PHOTOS

PHOTOS

This appendix provides photographs of Eastoke's Southern and Northern Frontages in the following order:

- Southern Frontage: Historic Photos
- Southern Frontage: Contemporary (3 November 2005 Flood Event)
- Northern Frontage: Contemporary (Pre-2005 Construction)
- Northern Frontage: New Works

SOUTHERN FRONTAGE: HISTORIC PHOTOS

These historic photos of the northern frontage show storm damage and overtopping of the beach before the current measures were implemented.



Photo 1 Overtopping flooding at Bembridge Drive 1978



Photo 2 Pre-1985 Wave overtopping seawall at Creek Road/Beach Club

SOUTHERN FRONTAGE: FLOOD EVENT OF 3 NOVEMBER 2005



Photo 3: Overtopping wave (view east)



Photo 4 View east along Southwood Road

NORTHERN FRONTAGE: PRE 2005 CONSTRUCTION



Photo 5: Sparkes Boatyard



Photo6: Variety of private defences protect properties from flooding at the western end of the creek

NORTHERN FRONTAGE: NEW WORKS

The following photos illustrate the new defences constructed along the northern frontage in spring 2005.



Photo 20: New rock revetment and slipway along southern frontage (12/07/05)



Photo 22: New floodgate and slipway (12/07/05)